

Airlink A/C N-TBO ITEM List OE-KFT

PA28RT-201T, S/N 28R-8431030, M/Y 1984

Page: 1/8

Inspector:

Flightlog: 11078

Date: 23.10.2024

Landings: 10445

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
05	Airframe Structure Modification for Camera installation	Installed per EO OE-KFT/4-6/93		22.04.2003
05	AT-1 FLARM Equipment	Installed per CS-STAN CS-SC051d / SC-002/24-OE-KFT		01.02.2024 10988 10289
05	Exchange of Basic Flight Instruments / Vacuum Removal	Installed per CS-STAN CS-SC401c / SC-001/24-OE-KFT		01.02.2024 10988 10289
05	Garmin Dual GI275 ADI / CDI	Installed per EASA STC 10075142 R3		01.02.2024 10988 10289
05	Garmin G500 PFD/MFD	STC Change to 10053008 Rev. 2 - Installed Per EASA STC 10029726 and HL/MOD/1050-02		06.05.2013 9735 8524
05	Garmin GFC500 Auto Pilot	Installed per EASA STC 10069439 Revision 7		01.02.2024 10988 10289
05	Garmin GNS430 COM/VOR/ILS/GPS	Installed per EMZ RC/SA 1122, upgraded via GAMA STC 10037701 R3		21.11.2008 9132 7327
05	Garmin GTX330 Transponder	Installed per MC EASA.A.C.04065		20.03.2007
05	Intercom System NAT AA80-001	Installed per MC 2005-871		01.02.2005

Inspector: Flightlog: 11078

Date: 23.10.2024

Landings: 10445

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
05	Kannad ELT 406AF	Installed per MC 2005-871		01.02.2025
05	King KX165A COM/NAV // AK550-6 DC-DC Converter	Installed per MC ASE-13-007-01		06.05.2013
				9735
				8524
22	Garmin GFC500 - GMC507	Installed per EASA STC 10069439 Revision 7	011-04548-01	01.02.2024
			included in 010-01946-01	10988
			5H1107375	10289
22	Garmin GFC500 - GSA28 w/ Ball Bearings - Pitch	Installed per EASA STC 10069439 Revision 7	011-02927-21	01.02.2024
			included in 010-01068-21	10988
			6N2018154	10289
22	Garmin GFC500 - GSA28 w/ Ball Bearings - Roll	Installed per EASA STC 10069439 Revision 7	011-02927-21	01.02.2024
			included in 010-01068-21	10988
			6N2017133	10289
22	Garmin GFC500 - GSA28 w/ Ball Bearings - Trim	Installed per EASA STC 10069439 Revision 7	011-02927-21	12.07.2024
			included in 010-01068-21	11039
			5G9005193	10360
22	Garmin GFC500 - Kit56, 2 Servo	Installed per EASA STC 10069439 Revision 7	K11-00024-56	01.02.2024
				10988
			NSN	10289
22	Garmin GFC500 - Kit57, Pitch Trim Servo	Installed per EASA STC 10069439 Revision 7	K11-00024-57	01.02.2024
				10988
			NSN	10289
24	Main Battery		RG-35AXC	18.05.2022
				10893
			# 41129996	10114

Inspector: Flightlog: 11078

Date: 23.10.2024

Landings: 10445

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
24	Voltage Converter	Installed per EASA STC 10029726	AK550-6	06.05.2013
				9735
			508319	8524
31	Oil Pressure Warning Light Switch		587-956	01.11.2023
				10984
			NSN	10281
32	Brake Disc LH	Parker Hannifin Corp.	164-0200	12.05.2020
				10749
			N/A	9938
32	Brake Disc RH	Parker Hannifin Corp.	164-0200	12.05.2020
				10749
				9938
32	Hydraulic Power Pack	Overhauled	Prestolite HYC 5005	01.07.2020
				10757
			78-0499	9955
32	MLG Tire RH	6.00-6	606C66-8	05.03.2019
			301-002-001	10550
			# 40547528	9658
32	MLG Tire LH	6.00-6	606C66-8	12.04.2019
				10597
			# 12647607	9734
32	RH Brake Linings		066-10500	01.11.2023
				10984
			NSN	10281
34	ADF	Mod: 1-3	King KR 87	
			066-1072-00	
			# 11430	

Inspector: Flightlog: 11078

Date: 23.10.2024

Landings: 10445

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
34	Airspeed Indicator		United Instrument	14.11.1996
			8125	
			# 161858	
34	Altimeter 1		United Instrument	31.08.2000
			5934PM-3	
			# 8K773	
34	Altimeter 2		United Instrument	31.08.2000
			5934PM-3	
			# 391004	
34	AT-1 FLARM	Installed per CS-STAN CS-SC051d / SC-002/24-OE-KFT	AT-1-(7301)	01.02.2024
				10988
			AT1-03171	10289
34	Bendix/King KX165A - COM/NAV 2	Installed per MC ASE-13-007-01	069-01033-0201	06.05.2013
			Mod 1-4	9735
			# 13229	
34	DME	Mod: 1-5	King KN 62 A	21.08.2008
			066-1068-01	
			# 2075	
34	ELT	Kannad 406 AF	S1821502-02	22.07.2005
			# P1273-0046	
34	ELT - Antenna		1327-82	22.07.2005
			# 3215	
34	ELT - Remote Control Panel	RC 100	S1820513-03	22.07.2005
			# 403246-0197	

Inspector: Flightlog: 11078

Date: 23.10.2024

Landings: 10445

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
34	Garmin G500 - GA35	Installed per EASA STC 10029726 - Changed to ST 10053008R2	013-00235-00	06.05.2013
				9735
			89529	8524
34	Garmin G500 - GDC74A	Installed per EASA STC 10029726 - Changed to ST 10053008R2	010-00336-10	06.05.2013
			011-00882-10	9735
			# 20614213	8524
34	Garmin G500 - GDU 620	Installed per EASA STC 10029726 - Changed to ST 10053008R2	010-00482-50	06.05.2013
				9735
			165202585	8524
34	Garmin G500 - GMU44 Magentometer / Fluxvalve	Installed per EASA STC 10029726 - Changed to ST 10053008R2	011-00870-00	22.08.2022
34	Garmin G500 - GRS77	Installed per EASA STC 10029726 - Changed to ST 10053008R2	010-00295-10	06.05.2013
				9735
			42021974	8524
34	Garmin G500 - GTP59	Installed per EASA STC 10029726 - Changed to ST 10053008R2	010-00978-00	06.05.2013
				9735
			47921780	8524
34	Garmin GI275 - ADI	Installed per EASA STC 10075142 R3	010-02326-10	01.02.2024
			includes 011-04489-10	10988
			5MZ117230	10289
34	Garmin GI275 - Battery Pack ADI	Installed per EASA STC 10075142 R3	010-02304-00	01.02.2024
			includes 011-04528-00	10988
			5MZ614640	10289
34	Garmin GI275 - CDI	Installed per EASA STC 10075142 R3	010-01912-10	01.02.2024
			includes 011-04489-10	10988
			5MZ113907	10289

Inspector: Flightlog: 11078

Date: 23.10.2024

Landings: 10445

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
34	Garmin GI275 - Connector Kit	Installed per EASA STC 10075142 R3	011-04809-01	01.02.2024
				10988
			NSN	10289
34	Garmin GI275 - GMU11 Magnetometer	Installed per EASA STC 10075142 R3	011-04349-01	01.02.2024
			Installation Kit: 011-04349-90	10988
			56J118246	10289
34	Garmin GI275 - GPS Antenna	Installed per EASA STC 10075142 R3	010-12444-10	01.02.2024
			includes 011-04036-10	10988
			641007604	10289
34	Garmin GI275 - GSB15	Installed per EASA STC 10075142 R3	010-02544-21	01.02.2024
			includes 011-04937-20	10988
			63M257487	10289
34	Garmin GI275 - Round Adapter Kit - 2ea	Installed per EASA STC 10075142 R3	011-05285-00	01.02.2024
				10988
			NSN	10289
34	Garmin GNS430 - GPS Antenna	Installed per EMZ RC/SA 1122	010-10040-01	21.11.2008
34	Garmin GNS430AW - COM/NAV/GPS 1	Installed per EMZ RC/SA 1122, upgraded via GAMA STC 10037701 R3	010-00413-01	06.05.2013
			including 011-01061-00	9735
			# 23520035	
34	Garmin GTX330 Transponder Mode S	Installed per MC EASA.A.C.04065	011-00455-00	25.03.2007
			Mod 1	
			# 84123517	
34	Marker Beacon Rec. / Audio Control Panel	Mod: 1,2,4,5	King KMA 24	21.08.2008
			066-1055-03	
			# 13200	

Inspector: Flightlog: 11078

Date: 23.10.2024

Landings: 10445

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
34	Turn Coordinator		1394T100-7Z	31.01.2005
				8085
			# G04-11789	6212
74	Spark Plugs	Replaced	RHM 38 E	04.10.2017
				10295
				9398
76	Control Mixture		455-361	11.04.2022
			PS50146-13-8	10893
77	EGT-Probe	Alcor	86240	21.02.2012
				9593
79	Oil Filler Cap		640620	15.05.2023
				10937
			NSN	10193
98	Attitude Gyro	Removed by Garmin GI275 installation	King KG - 258	01.02.2024
			060-0020-01	
			# 9180	
98	Autopilot KFC 150	Removed by Garmin GFC500 installation	King KC 191	01.02.2024
			065-0054-02	
			# 20525	
98	Blind Encoder	Removed by Garmin GFC500 installation	SAE5-35	01.02.2024
			013-00066-00	
			# 6547	
98	Directional Gyro	Removed by Garmin GI275 installation	King KG - 102 A	01.02.2024
			060-0015-00	10988
			# 47987	10289

Inspector: Flightlog: 11078

Date: 23.10.2024

Landings: 10445

ATA-Nr.	Component	Remark	P/N	Instal. Date
			Alt. P/N	A/C-Hrs
			S/N	Ldgs
98	H S I	Removed by Garmin GI275 installation	KI 525A	01.02.2024
			066-3046-07	
			# 81799	
98	Pitch - Servo	Removed by Garmin GFC500 installation	King KS 177	01.02.2024
			065-0050-06	
			# 4015	
98	Roll - Servo	Removed by Garmin GFC500 installation	King KS 178	01.02.2024
			065-0051-06	
			# 1613	
98	Trim - Servo	Removed by Garmin GFC500 installation	King KS 179	01.02.2024
			065-0052	
			# 1622	